
## PARTS LIST FOR NO. 3 SERIES PISTOL AND "T" HANDLE DRILLS



1					
Fig. Part			Fig.	Part	
	No. No	. Description	No.	No.	Description
1.	21002	Chuck (3/8" Cap .)		22640	Spindle—Chuck (2650 RPM)(Non-Reversing)
	21137	Chuck (1/2" Cap.)			(Includes 08310 Screw)
	08310	Screw—L.H. (Serial "C" & Up)(Reversing	12.	25976	Washer
		Units)	13.	10203	Bearing—Ball
	30011	Key—Chuck (Used with either chuck.)	14.	30467	Pin (2)*
2.	44914	Retainer	15.	53724	Ass'y—2nd Planetary Gear
3.	10198	Bearing—Ball			(1800 RPM)(Reversing)(Includes 08310 Screw)
4.	44798	Sleeve—Lock		43873	Ass'y—2nd Planetary Gear
5.	30258	Seal—Oil			(2150 RPM)(Non-Reversing)
6.	30375	Fitting—Grease		53723	Ass'y—2nd Planetary Gear
7.	44799	Case—Gear			(2250 RPM)(Reversing)(Includes 08310 Screw)
8.	44795	Pin		43872	Ass'y—2nd Planetary Gear
9.	19327	Ass'y—Gear & Bearing			(2650 RPM)(Non-Reversing)
		(1800 & 2150 RPM)(2)*	16.	19208	Gear—Ring
	19324	Ass'y—Gear & Bearing	17.	41236	Washer
		(2250 & 2650 RPM)(2)*		53731	Ass'y—Gear Case (1800 RPM)(Reversing)
11.	22656	Spindle—Chuck (1800 RPM)(Reversing)		43875	Ass'y—Gear Case (2150 RPM)(Non-Reversing)
		(Includes 08310 Screw)		53730	Ass'y—Gear Case (2250 RPM)(Reversing)
	44808	Spindle—Chuck (2150 RPM)(Non-Reversing)		43876	Ass'y—Gear Case (2650 RPM)(Non-Reversing)
	22657	Spindle—Chuck (2250 RPM)(Reversing)			
		(Includes 08310 Screw)	l		*Order Quantity As Needed